



Brand:	Citroen	Mileage(km):	39122
Model:	Berlingo	Number of doors:	5
Model type:	1.2 130PK Shine Aut.	Vehicle length (cm):	
License plate:	725208	Vehicle width (cm):	
Report code:	5208	Vehicle height (cm):	
Chassis number:	VR7ERHNS3LJ725208	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	21/07/2020	Power(kw):	96
First NL reg.:		Transmission:	Automatic
Color:	White <input type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Daytime running lights
- Licht Sensor
- ABS
- Central locking system
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Halogen headlights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- 360 ° camera system
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- USB connection
- Bluetooth streaming
- Cruise control
- Climate control (analog)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Switch flippers
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Steel	/	tourador	7
Tire left rear	All weather	Steel	/	tourador	7
Tire right front	All weather	Steel	/	tourador	7
Tire right rear	All weather	Steel	/	tourador	7

Additional information

No. of keys:	1 <input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Miscellaneous	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Front bumper - Paint repair



Front left door - Paint repair



Left outside mirror - Scratch

🔍 Claimed fields

€
0

Voorbumper / Lakherstel /

€
0

LV portier / Lakherstel /

€
0

Buitenspiegel links / Kras(sen) /

€
0

⚙️ Extra options



