



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	71765
<b>Model:</b>	2008	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 110 GT Line aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	L465BG	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	9113	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF3CUHNPNKY089113	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	03/05/2019	<b>Power(kw):</b>	81
<b>First NL reg.:</b>	09/05/2021	<b>Transmission:</b>	Automatic
<b>Color:</b>	White <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	6
<b>Weight (kg)(ka):</b>	1265	<b>Displacement(cc):</b>	1199
<b>Empty weight(ka):</b>	1165	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	254	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	187	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	D
<b>Average consumption (l/100 km):</b>	5.5	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	10.5	<b>CO2 (g/km):</b>	126
<b>Cargo space (l):</b>	1265	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1680	<b>APK date:</b>	03/05/2025

## opties

- |  |   |   |
|--|---|---|
| <input checked="" type="checkbox"/> Alloy wheels                       | <input checked="" type="checkbox"/> Rain sensor                       | <input checked="" type="checkbox"/> Climate control (analog)            |
| <input checked="" type="checkbox"/> Daytime running lights             | <input checked="" type="checkbox"/> Rear wiper                        | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Licht Sensor                       | <input checked="" type="checkbox"/> Rear view camera                  | <input checked="" type="checkbox"/> Electrically operated rear windows  |
| <input checked="" type="checkbox"/> ABS                                | <input checked="" type="checkbox"/> Rear parking sensors              | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Dynamic bend lighting              | <input checked="" type="checkbox"/> Rear-seat folding (equal parts)   | <input checked="" type="checkbox"/> Electrically folding mirrors        |
| <input checked="" type="checkbox"/> Fog lamps                          | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Power steering                     | <input checked="" type="checkbox"/> Luggage cover                     | <input checked="" type="checkbox"/> Sport seats                         |
| <input checked="" type="checkbox"/> Multifunctional steering wheel     | <input checked="" type="checkbox"/> Spare wheel (full)                | <input checked="" type="checkbox"/> Extendable passenger seat           |
| <input checked="" type="checkbox"/> Remote central locking             | <input checked="" type="checkbox"/> USB connection                    | <input checked="" type="checkbox"/> Extendable driver's seat            |
| <input checked="" type="checkbox"/> Roof rail (silver)                 | <input checked="" type="checkbox"/> Bluetooth streaming               | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Roof rail (black)                  | <input checked="" type="checkbox"/> DAB+                              | <input checked="" type="checkbox"/> Leather steering wheel              |
| <input checked="" type="checkbox"/> Metallic finish                    | <input checked="" type="checkbox"/> Bluetooth car kit                 | <input checked="" type="checkbox"/> Lane assistance                     |
| <input checked="" type="checkbox"/> Halogen headlights                 | <input checked="" type="checkbox"/> Radio                             | <input checked="" type="checkbox"/> Dead angle assistance               |
| <input checked="" type="checkbox"/> LED rear lights                    | <input checked="" type="checkbox"/> WiFi                              | <input checked="" type="checkbox"/> Airbag(s) front                     |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control                    | <input checked="" type="checkbox"/> Airbag(s) front + flank             |
| <input checked="" type="checkbox"/> Privacy glass                      | <input checked="" type="checkbox"/> Climate control                   | <input checked="" type="checkbox"/> Airbag(s) front + flank + other     |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	/	Goodyear	6
Tire left rear	Summer	Alloy	/	Goodyear	5
Tire right front	Summer	Alloy	/	Goodyear	6
Tire right rear	Summer	Alloy	/	Goodyear	4

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(door dealer, serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	16/11/2023	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	61792	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- Clean inside (Interior is clean)

Clean outside

 Damages

 Not acceptable

 Damages

 Acceptable



Front left rim - Scratch



Front bumper - Paint repair



Front right rim - Scratch



Rear right rim - Scratch

 Claimed fields

€  
0

LV velg / Kras(sen) /

€  
0

Voorbumper / Lakherstel /

€  
0

RV velg / Kras(sen) /

€  
0

RA velg / Kras(sen) /

€  
0

 Extra options



