



| | | | |
|---|---|-----------------------------|---------------------------------------|
| Brand: | Kia | Mileage(km): | 58690 |
| Model: | Niro | Number of doors: | 5 |
| Model type: | 1.6 GDi Hybrid DynamicPlusLine | Vehicle length (cm): | |
| License plate: | L398SJ | Vehicle width (cm): | |
| Report code: | 8672 | Vehicle height (cm): | |
| Chassis number: | KNACC81CGM5458672 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 02/08/2021 | Power(kw): | 77 |
| First NL req.: | 02/08/2021 | Transmission: | Automatic |
| Color: | Black <input checked="" type="checkbox"/> Metallic | Number of gears: | 6 |
| Weight (kg)(kg): | 1490 | Displacement(cc): | 1580 |
| Empty weight(kg): | 1390 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 270 | Fuel type: | Hybride (Electro/Benzine) non plug-in |
| Top speed (km/h): | 162 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 3.4 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 4 | Energy label: | A |
| Average consumption (l/100 km): | 3.7 | NL Tax Rate %: | |
| Acceleration (s): | 11.5 | CO2 (g/km): | 86 |
| Cargo space (l): | 1490 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1930 | APK date: | 02/08/2025 |

🔧 opties

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Leather upholstery | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Spare wheel (full) | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Heated steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Cruise control (adaptive) | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control | <input checked="" type="checkbox"/> Dead angle assistance |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (analog) | <input checked="" type="checkbox"/> Airbag(s) front |
| <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Large screen navigation | <input checked="" type="checkbox"/> Airbag(s) front + flank |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Keyless entry | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |
| <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Keyless entry/start/stop | |

🔧 Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Alloy | / | Michelin | 4 |
| Tire left rear | Summer | Alloy | / | Michelin | 5 |
| Tire right front | Summer | Alloy | / | Michelin | 4 |
| Tire right rear | Summer | Alloy | / | Michelin | 5 |

⚠️ Additional information

| | | | | |
|--------------------------|-------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (door universeel, serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 26/01/2024 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 46692 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

⚠️ Cleaning

Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊗ Not acceptable

🔧 Damages

⊗ Acceptable



Rear bumper - Scratch



Rear bumper - Dent

🚩 Claimed fields

€ 0

Achterbumper / Kras(sen) /

€ 0

Achterbumper / Deuk(en) /

€ 0

⚙️ Extra options



