



Brand:	Volkswagen	Mileage(km):	93042
Model:	Touran	Number of doors:	5
Model type:	1.5 TSI Comfortline Business 7p Aut.	Vehicle length (cm):	
License plate:	XD154X	Vehicle width (cm):	
Report code:	6675	Vehicle height (cm):	
Chassis number:	WVGZZ1TZKW016675	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	08/01/2019	Power(kw):	110
First NL req.:	08/01/2019	Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	7
Weight (kg)(kg):	1550	Displacement(cc):	1498
Empty weight(kg):	1450	Number of cylinders:	4
Wheelbase (cm)(cm):	279	Fuel type:	Petrol
Top speed (km/h):	209	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.9	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.9	Energy label:	C
Average consumption (l/100 km):	5.7	NL Tax Rate %:	
Acceleration (s):	8.9	CO2 (g/km):	129
Cargo space (l):	1550	Nb. of Axles:	2
Perm. max weight (kg):	2250	APK date:	08/01/2025

opties

- Alloy wheels
- Daytime running lights
- Licht Sensor
- ABS
- Dynamic bend lighting
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Roof rail (silver)
- Roof rail (black)
- Metallic finish
- Halogen headlights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Baggage separation net
- Luggage cover
- Trunk opens electrically
- Aux connection
- USB connection
- Bluetooth streaming
- DAB+
- Radio/CD player
- Bluetooth car kit
- Radio
- Cruise control (adaptive)
- Cruise control
- Airconditioning in the back
- Climate control
- Climate control (analog)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Massage function driver's seat
- Massage function passenger seat
- Central armrest front
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Leather steering wheel
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	/	Pirelli	6
Tire left rear	Summer	Alloy	/	Pirelli	5
Tire right front	Summer	Alloy	/	Pirelli	5
Tire right rear	Summer	Alloy	/	Pirelli	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	7	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	7	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊗ Not acceptable

🔧 Damages

⊗ Acceptable



Rear bumper - Paint repair



Rear left door - Dent



Rear left screen - Paint repair



Front bumper - Paint repair




Front bumper - Paint repair



Front bumper - Paint repair



Front bumper - Break



Front left door - Dent



Front right rim - Scratch

🔧 Claimed fields

€ 0

Achterbumper / Lakherstel /

€ 0

LA portier / Deuk(en) /

€ 0

LA scherm / Lakherstel /

€ 0

Voorbumper / Lakherstel /

€ 0

Voorbumper / Lakherstel /

€ 0

Voorbumper / Lakherstel /

€ 0

Voorbumper / Breuk /

€ 0

RV portier / Deuk(en) /

€ 0

RV velg / Kras(sen) /

€ 0

