



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	46695
<b>Model:</b>	208	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 130 GT Line aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	91010	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	1010	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VR3UPHNSSKT091010	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	26/02/2020	<b>Power(kw):</b>	
<b>First NL reg.:</b>		<b>Transmission</b>	Automatic
<b>Color:</b>	<input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	
<b>Weight (kg)(ka):</b>		<b>Displacement(cc):</b>	1199
<b>Empty weight(ka):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Avarage consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- Alloy wheels
- Digital dashboard
- Daytime running lights
- Licht Sensor
- ABS
- Start/stop system
- Front seats adjustable in height
- Multifunctional steering wheel
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- 360 ° camera system
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (full)
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Radio
- Cruise control
- Black top interior
- Climate control (analog)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	/	Michelin	6
Tire left rear	Summer	Alloy	/	Michelin	5
Tire right front	Summer	Alloy	/	Michelin	5
Tire right rear	Summer	Alloy	/	Michelin	5

### Additional information

<b>No. of keys:</b>	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(door dealer, serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	19/09/2023	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	35242	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Front left door - Dent



Front right rim - Scratch



Front left rim - Scratch

📄 Claimed fields

€ 0

RV portier / Deuk(en) /

€ 0

RV velg / Kras(sen) /

€ 0

LV velg / Kras(sen) /

€ 0

⚙️ Extra options



