



Brand:	Skoda	Mileage(km):	52917
Model:	Kodiaq	Number of doors:	5
Model type:	1.5 150PK Style Aut. Pano	Vehicle length (cm):	
License plate:	517429	Vehicle width (cm):	
Report code:	7429	Vehicle height (cm):	
Chassis number:	TMBJB7NS1N8517429	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	28/11/2022	Power(kw):	110
First NL req.:		Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1500
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- ABS
- Fog lamps
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- Panoramic roof (electrical)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Ski hatch
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control (adaptive)
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Switch flippers
- Heated steering wheel
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	/		4
Tire left rear	All weather	Alloy	/		6
Tire right front	All weather	Alloy	/		4
Tire right rear	All weather	Alloy	/		6

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	7	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	7	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages


⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Linker Led Koplamp Defect



Windscreen - Pip



Rear bumper - Scratch



Rear left door - Scratch

📁 Claimed fields

€
0

Linker Led Koplamp Defect / Repareren
toevoegen

€
0

Voorruit, Voorruit / Ster, Ster / Opvullen

€
0

Achterbumper, Achterbumper /
Kras(sen), Kras(sen) / Bijwerken

€
0

LA portier, LA portier / Kras(sen),
Kras(sen) / Polijsten

€
0

⚙️ Extra options

