Inspected by: Herman ATS ATS



Brand:	Citroen	Mileage(km):	44915
Model:	C3 Aircross	Number of doors:	5
Model type:	1.2 130PK Shine Aut. Pano	Vehicle length (cm):	
License plate:	373392	Vehicle width (cm):	
Report code:	3392	Vehicle height (cm):	
Chassis number:	VF72RHNS1M4373392	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	15/12/2021	Power(kw):	96
First NL req.:		Transmission	Automatic
Color:	Black Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties opties

Alloy wheels SCREGGESCASSCRES Licht Sensor

ABS

Fog lamps Start/stop system

Power steering

Multifunctional steering wheel

Remote central locking

Roof rail (black)

Metallic finish

Panoramic roof (electrical)

LED headlights

LED rear lights

Privacy glass Rain sensor

Rear view camera

Rear parking sensors

Rear wiper
Rear view of
Rear parkin
Front parkin Front parking sensors Towbar with fixed ball

Rear-seat folding (unequal parts) ${f \checkmark}$

\ \ \ Ski hatch

Luggage cover

Inflatable set

USB connection

Bluetooth streaming

DAB+
Bluetooth car k
Radio
Cruise control Bluetooth car kit

Large screen navigation

Climate control (digital)
Large screen navigation
Keyless entry/start/stop
Electrically operated rea
Electrically operated fror Keyless entry/start/stop

Electrically operated rear windows

Electrically operated front windows

Electrically folding mirrors

Electrically adjustable mirrors

Electrically heated driver's seat Electrically heated passenger seat

Central armrest front

Audio control on the steering wheel

Leather steering wheel

Lane assistance

Airbag(s) front + flank + other

🗱 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/50 R17	Bridgestone	4
Tire left rear	Summer	Alloy	215/50 R17	Bridgestone	6
Tire right front	Summer	Alloy	215/50 R17	Bridgestone	4
Tire right rear	Summer	Alloy	215/50 R17	Bridgestone	6

Additional information

No. of keys:	1 Luxury key	Instruction booklet	✓ Airco works
Interior color:	Anthracite	Maintenance booklet:	Odorless
Upholstery:	Half stof/leder		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	✓ Vehicle special usage (None)

A Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable







Rear bumper - Scratch



Front bumper - Scratch



Rear left door - Paint repair

در Damages





Front left screen - Restyle dent



Front left door - Restyle dent

Claimed fields

Achterbumper / Kras(sen) / Spuiten







LV scherm / Restyle Deukje(s) / Restylen € 0



LA portier / Lakherstel / Spuiten





€ 0

🗱 Extra options




















































AUTOF CTOR