



Brand:	Skoda	Mileage(km):	63990
Model:	Fabia Combi	Number of doors:	5
Model type:	1.0 TSI Style	Vehicle length (cm):	
License plate:	H225VP	Vehicle width (cm):	
Report code:	2474	Vehicle height (cm):	
Chassis number:	TMBJP6NJXLZ102474	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	04/06/2020	Power(kw):	70
First NL reg.:	04/06/2020	Transmission:	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears:	5
Weight (kg)(ka):	1136	Displacement(cc):	999
Empty weight(kg):	1036	Number of cylinders:	3
Wheelbase (cm)(cm):	247	Fuel type:	Petrol
Top speed (km/h):	185	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.8	Energy label:	B
Average consumption (l/100 km):	4.5	NL Tax Rate %:	
Acceleration (s):	10.9	CO2 (g/km):	103
Cargo space (l):	1136	Nb. of Axles:	2
Perm. max weight (kg):	1591	APK date:	04/06/2026

opties

- | | | |
|--|---|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable passenger seat |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (analog) | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/45 R16	Kumho	5
Tire left rear	Summer	Alloy	215/45 R16	Kumho	7
Tire right front	Summer	Alloy	215/45 R16	Kumho	5
Tire right rear	Summer	Alloy	215/45 R16	Kumho	7

Additional information

No. of keys:	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Front right rim - Scratch



Rear right screen - Scratch

🔧 Damages

⊕ Acceptable

👉 Claimed fields

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0


RV velg / Kras(sen) / Spuiten


€ 0

RA scherm / Kras(sen) / Spuiten

€ 0

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE